

BUILDING SAFETY CERTIFICATE

No. 970

Dated: 12/12/2022

Certified that the existing building Corolla Public School at Bhagat Sing Ward, Multai, Dist Betul (M.P) comprised of Ground Floor, First Floor, second floor owned/occupied by Devi Urmila Shiksha Samiti, Gayatri Nagar, Multai, Dist Betul, MP have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of **R.K. RAI, Sub Dn. Officer** (Name of Department/Govt.) on **P.W.D.** in the presence of **Shri Surendera Singh Rathore** and that the building/premises is fit for occupancy upto classes XII with effect from **12/12/2022** for a period of **5** yearfs in accordance with rule and subject to compliance of the specific conditions as appended.

1. Opening Safe
2. Fire extinguisher sufficient
3. Both male & Female Toilet Present
- 4.

Issued on 12/12/2022

*Strike out whichever is not applicable.


Signature with Seal: _____


Name: **R.K. Rai**Designation :- **S.D.O.**

Sub. Divisional Officer
P.W.D. (BIR) Sub division
MULTAI

Name & Address of Department/Office:-**P.W.D. Sub Division Multai**

(Assistant Engineer & above officer of concerned Govt. Department only)


सचिव
देवी उर्मिला शिक्षा समिति


Principal
Corolla Public School
Multai